ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward

Street ID	Street Name	Significant Landmark
W0394, W0404, W0398, W0388, W0327, W0380, W0396	3rd Crs, NA, 4th Crs, Doddamuniswammppa Lyt, 3rd Crs, Lakshmi Sagar Lyt North Side, 2nd Crs, 9th Cr	Gandhinagara near Rajaraeshwari Kalayana Mantapa

Segment No.	Total Length (m)
1/C-W0394/S112718	175.74

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	58.06	77.594363	13.098902	77.594875	13.098771	W0327	RAILWAY LINE
2	117.68	77.595166	13.099314	77.594776	13.098323	W0380	W0404

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Drain and CC Road at opposite to ICICI bank Construction Drain at Gandhinagara near Rajaraeshwari Kalayana Mantapa in ward no 01 Yelah	1990000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Construction of Drain and CC Road at opposite to ICICI bank Construction Drain at Gandhinagara near Rajaraeshwari Kalayana Mantapa in ward no 01 Yelahanka Sub-Division Yelahanka zone	001-16-000013

Work Order No.	Work Order Date	Period of Extention
EE(YNK D)E-PMT-1/WO/28/2015-16	24/02/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
24/02/2016	23/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

S B M

No.

E-Mail ID

0.00

122827

eld Inspection Details

Number of Trees	Any Other Information	Name
2		CHANDRASHEKAR
Date of Inspection	**Remarks**	
03/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0394, W0404, W0398, W0388,

rain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	VASU K M	03/12/2016	02/01/2017	COMPLETED
AEE	G.B. PRABHAKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0394, W0404, W0398, W0388,